


FORM 101 AMP-TRAP FUSE  
 MELTING TIME CURRENT DATA  
 15-2000 AMPS 1000 VOLTS  
 CAT. NO. A100P(15-30) TYPE-1  
 A100P(35-2000) TYPE-4, 4IL, 4TA, 4TI

FERRAZ SHAWMUT  
 NEWBURYPORT, MA 01950

96313



CONTROL NO: 1005  
 REV: N  
 FOLDER NO.: 1G  
 DATE: 6-6-06